

Subject

Door control TS 971 – Discontinuation of second UBS socket

Description


In preparation for the new, modern data interface, for the door control TS 971 (❶), the second UBS¹⁾ socket (❷) is discontinued.



To this end, the TS 971 will have only one UBS socket (❸) as is currently the case already with the door control TS 970. The UBS system can continue to be used as usual with electric UBS components such as control devices, loop detectors or photo cells.

More information regarding the data interface and its operability is published in a separate Technical Information sheet.

Figure



Notes

- The changeover will take place starting 05/2022.
- Mixed deliveries may happen due to inventories.

Do you have any further questions on the topic? Your sales representative will gladly advise you:

<http://gfa-elektromaten.com/en-DE/contact.html>

1) UBS: Universal command sensor system