

GfA Service case

Description

The GfA service case allows the efficient and cost-effective fault analysis on site. If the drive or control system at the door is compromised, the components of the service case assist you in structured error analysis and repair. The service case contains for example: GfA-Stick to read out door controls TS 959,

TS 970 or TS 971 by smart phone or laptop, reference control TS 971 and other components such as a digital limit switch, WSD door-module or OSE set that allow narrowing down error causes. The package also includes extensive documentation.

Service case



Designation

Service case

Part no.

20004007.00001

	Content		Part no.
1.	Case	A	40019255
2.	GfA-Stick	B	20003696
3.	Voltcraft digital multimeter (Voltage and current measuring device)	C	40019256
4.	Door control TS 971 (with connection kit, when hardwired)	D	20097100.00001
5.	WSD door module with battery	E	30005154
6.	Spiral cable with junction box	F	20002620.00001
7.	Digital limit switch DES 4	G	30004757
8.	Universele OSE-set 0,5m	H	30005185.00060
9.	OSE tester	I	40019272
10.	Rubber profile OSE 0,2m		30005119.00020
11.	Connection cable 6,5m for OSE	J	20002630.00650
12.	Rectifier EGR II	K	20003369.00001
13.	Resistor 8k2		40005736
14.	Operating and installation instructions (e.g. for TS 970, TS 971, WSD)		
15.	Additional documents for structured fault diagnostics		



Notice:

If you need additional advice on site, please find your technical support adviser via GfA website:

<http://gfa-elektromaten.com/en/DE/contact.html>